Click On Part Number To Order

Sec. 02

CAP SCREWS

24005



Zinc Plated

Hex Head Body Tap Bolt
3/8"-16 x 2"
Grade 2
Full Thread

UNIT PACKAGE: 100



Grade 5

Bright Zinc Chromate Medium Carbon Heat Treated Steel



120,000 P.S.I. Minimum Tensile Strength, Head is Identified with 3 Radial Lines
Part No. Part No. Unit Part No. Part No. Unit

Size	Part No. U.S.S.	Part No. S.A.E.	Unit Pkg.	
1/4"	1/4" U.S.S. (Coarse) Threads Per Inch: 20 S.A.E. (Fine) Threads Per Inch: 28			
1/,4 x 1/2"	*5434	*5495	100	
1/4 x 5/8"	*5435	#5.407	100	
1/4 x 3/4"	*5436 *5430	*5497 *5400	100	
1/4 x 1" 1/4 x 1-1/4"	*5438 5439	*5499 5500	100	
1/4 x 1-1/2"	5440	5501	100	
1/4 x 1-3/4"	5441	0001	100	
1/4 x 2"	5442		100	
1/4 x 2-1/4"	5443		100	
1/4 x 2-1/2"	5444	5505	100	
1/4 x 2-3/4"	5445		100	
1/4 x 3" 1/4 x 3-1/2"	5446 8449		100	
1/4 X 3-1/2	0449		100	
5/16"	U.S.S. (Coarse) 1 S.A.E. (Fine) T	Threads Per Inc hreads Per Inc	:h: 18 h: 24	
5/16 x 1/2"	*5447		100	
5/16 x 5/8"	*5448		100	
5/16 x 3/4"	*5449	*5510	100	
5/16 x 7/8"	*5450	*5510	100	
5/16 x 1"	*5451 *5452	*5512	100 100	
5/16 x 1-1/4" 5/16 x 1-1/2"	*5452 5453	5514	100	
5/16 x 1-3/4"	5454	3314	100	
5/16 x 2"	5455	5516	50	
5/16 x 2-1/4"	5456		50	
5/16 x 2-1/2"	5457		50	
5/16 x 3"	5459		50	
5/16 x 4"	8450		50	
3/8"	U.S.S. (Coarse) 1 S.A.E. (Fine) T	Threads Per Inc hreads Per Inc	:h: 16 h: 24	
3/,8 x 5/,8"	*5462		50	
3/8 x 3/4"	*5463	*5524	50	
3/8 x 7/8"	*5464	*5500	50	
3/8 x 1" 3/8 x 1-1/4"	*5465 *5466	*5526 *5527	50 50	
3/8 x 1-1/2"	5467	5528	50	
3/8 x 1-3/4"	5468	3320	50	
3/8 x 2"	5469	5530	50	
3/8 x 2-1/4"	5470		50	
3/8 x 2-1/2"	5471		50	
3/8 x 3"	5472		50	
3/8 x 3-1/2"	5473		50	
3/8 x 4" 3/8 x 4-1/2"	5474 8096		50 25	
3/8 x 5"	8097		25	
O/O X O	3037		20	

Size	Part No. U.S.S.	Part No. S.A.E.	Pkg.	
7/16"	U.S.S. (Coarse) Threads Per Inch: 14 S.A.E. (Fine) Threads Per Inch: 20			
7/16 x 3/4"	*5475		50	
7/16 x 1"	*5476	*5537	50	
7/16 x 1-1/4"	*5477	*5538	50	
7/16 x 1-1/2"	*5478	*5539	50	
7/16 x 1-3/4"	5479		50	
7/16 x 2"	5480		25	
7/16 x 2-1/2"	5481	5542	25	
7/16 x 3"	5482		25	
7/16 x 3-1/2"	5483		25	
7/16 x 4"	5484		25	
1/2"	U.S.S. (Coarse) Threads Per Inch: 13			

$\begin{array}{cccccccccccccccccccccccccccccccccccc$	S.A.E. (Fine) Threads Per Inch: 20		
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	50		
1/2 x 1-1/2"	50		
1/2 x 1-3/4" *5489 *5550 1/2 x 2" 5490 5551 1/2 x 2-1/2" 5491 1/2 x 3" 5492 5553 1/2 x 3-1/2" 5493 1/2 x 4" 5494	50		
1/2 x 1-3/4" *5489 *5550 1/2 x 2" 5490 5551 1/2 x 2-1/2" 5491 1/2 x 3" 5492 5553 1/2 x 3-1/2" 5493 1/2 x 4" 5494	25		
1/2 x 2" 5490 5551 1/2 x 2-1/2" 5491 1/2 x 3" 5492 5553 1/2 x 3-1/2" 5493 1/2 x 4" 5494	25		
1/2 x 3" 5492 5553 1/2 x 3-1/2" 5493 1/2 x 4" 5494	25		
1/2 x 3-1/2" 5493 1/2 x 4" 5494	25		
1/2 x 4" 5494	25		
	25		
-1	25		
$1/2 \times 4 - 1/2''$ 8104	25		
1/2 x 5" 8105	25		
1/2 x 6" 8107	25		

5/8"	U.S.S. (Coarse) Threads Per Inch: 11 S.A.E. (Fine) Threads Per Inch: 18		
5/8 x 1"	*9520	25	
5/8 x 1-1/2"		*9528 25	
5/8 x 2"	*9522	25	
5/8 x 3"	9524	25	
5/8 x 3-1/2" 5/8 x 4"	9525	25	
5/8 x 4"	9526	25	
3/4"	U.S.S. (Coarse) Thred	ıds Per Inch: 10	
0/4 0"	*0.450	10	

3/4 x 2"	*8453	10
3/4 x 2-1/2"	*8454	10
3/4 x 3"	8455	10
2/1 / 2-1/2"	9.456	10

*Items threaded to head

▲WARNING: ALL ITEMS IN CHART Reproductive Harm & Cancer www.P65Warnings.ca.gov

Refer to assortment 1020 in the green pages